# **Commercial Metal Building Services Corp**

Project Issues Report

Project: Miami Executive Air

Report Date: Sunday, August 18, 2013 Produced By: Dean S. Davids

## **Open Issues**

Type: Punchlist		
PCCX Channels	At Endwall Columns	Friday, July 5, 2013
	Never yet installed at top of column connection to purlins. We can't find the channels. It seems they have been moved or taken. Still looking.	
Two Small Frame	ed Openings In Lean To Wall	Saturday, July 6, 2013
Description:	Mario says he can't find material for it. I found the channels out on the Tarmac	. The trim is inside the
	building.	
Monday, July 8, 2013	Attempted to verify locations with Omar. He says there should be a third one. We have material for only	two. Two are shown on the drawing.
	Omar is going to review architectural drawing to see if they match erection drawing location.	
Thursday, July 11, 2013	Frames are in but we haven't cu the sheeting.	
Remove Stifflegs	, Insulation	Saturday, July 6, 2013
Description:	On the West wall, specifically but check elsewhere.	
Monday, July 8, 2013	Insulation is gone. I reminded Ismael about the board.	
Finish Downspou	uts	Friday, July 12, 2013
Description:	Lowest section and elbows were left off to complete after grading is done.	

scription: Lowest section and elbows were left off to complete after grading is done.

## **Closed Issues**

Anchor Bolts Re	ady Letter	Wednesday, May 8, 201
Description:	Per FS 1926.752, erector is required to have a letter from the	5 , 5
	concrete is sufficiently cured and that the anchor bolts are r	, , ,
	loads prior to starting to erect columns. Erector is also to be were modified or repaired.	e notified, in writing, if any of the anchor bolts
	I have asked Andrew for this letter on several occasions priv	or to today but have not yet received it. I have
	been told, verbally that the site is ready and we have a full of	crew on site today, prepared to start erecting
	but we are waiting for the confirmation prior to moving forw	ard with columns.
	Andrew responded to my email with direction that we can s	set on the part of the slab that was set earlier.
	According to his email, rest of the slab is ours on Monday.	
Wednesday, May 8, 2013		
Monday, May 13, 2013	Andrew confirmed in email that we can start erecting columns at the West side columns today. That slab was poured Friday.	wall today. He also stated that we can erect the lean-to
Type: Detail		
Foam Generator	Locations	Wednesday, May 8, 201
		Wednesday, May 0, 201
	Foam generator support beams are field located. Plans sho	
		w only approximate locations. We will need
	Foam generator support beams are field located. Plans sho these locations provided within the next few days as we sta James sent drawing with dimensions just before lunch.	w only approximate locations. We will need
Description: Wednesday, May 8, 2013	Foam generator support beams are field located. Plans sho these locations provided within the next few days as we sta James sent drawing with dimensions just before lunch. Issue Closed	w only approximate locations. We will need art assembling grids.
Description:	Foam generator support beams are field located. Plans sho these locations provided within the next few days as we sta James sent drawing with dimensions just before lunch. Issue Closed	w only approximate locations. We will need art assembling grids. drawn, will be directly over roof bracing angles. The foam
Description: Wednesday, May 8, 2013	Foam generator support beams are field located. Plans sho these locations provided within the next few days as we sta James sent drawing with dimensions just before lunch. Issue Closed Laying out the the locations for installation, found that some of the frames, as o generators I have seen on other jobs have large cone shape dispersers hanging	w only approximate locations. We will need art assembling grids. drawn, will be directly over roof bracing angles. The foam g below the curb. If this is the case, the roof bracing will and there does not appear to be any subframing between the
Description: Wednesday, May 8, 2013 Saturday, May 25, 2013 Saturday, May 25, 2013	Foam generator support beams are field located. Plans sho these locations provided within the next few days as we sta James sent drawing with dimensions just before lunch. Issue Closed Laying out the the locations for installation, found that some of the frames, as d generators I have seen on other jobs have large cone shape dispersers hanging interfere with installation. Additionally, the erection drawings do not give a distance between the beams a beams. I am hesitant to install the beams without looking into the details and co between the beams. Issue Status Open- Follow Up Required	w only approximate locations. We will need art assembling grids. drawn, will be directly over roof bracing angles. The foam g below the curb. If this is the case, the roof bracing will and there does not appear to be any subframing between the onfirming placement. At the least, we need a dimension
Description: Wednesday, May 8, 2013 Saturday, May 25, 2013	Foam generator support beams are field located. Plans sho these locations provided within the next few days as we sta James sent drawing with dimensions just before lunch. Issue Closed Laying out the the locations for installation, found that some of the frames, as of generators I have seen on other jobs have large cone shape dispersers hanging interfere with installation. Additionally, the erection drawings do not give a distance between the beams a beams. I am hesitant to install the beams without looking into the details and co between the beams. Issue Status Open-Follow Up Required Andrew sent drawing with detail. The beams need to be 65" clear between ther by the angle braces.	w only approximate locations. We will need art assembling grids. drawn, will be directly over roof bracing angles. The foam g below the curb. If this is the case, the roof bracing will and there does not appear to be any subframing between the onfirming placement. At the least, we need a dimension

972 West Prospect Road, Fort Lauderdale, FL 33309 954-492-0661 954-492-0664

Purlin Schedule	Conflict Wednesday, May 15, 2
Description:	Looking at the roof secondary plan, purlins at the endbays appear to be spaced the same as in the field. Looking at the frame cross sections for lines .9, 1 and 2, there are additional strut purlins shown with varied spacings.
	We need clarification or additional details and part numbers to resolve the conflict.
	Called James at Lemartec, awaiting call back.
Thursday, May 16, 2013 Thursday, May 16, 2013	VP sent revised drawing indicating the additional members are the door support members.
rack Support D	Detail Thursday, May 16, 2
Description:	DH03X5 and DH04X5 details show a welded clip connection of the the track support beam to the end
	posts. The clip is called out as ABX014.
	We have a stack of 110 angles, unmarked, that appears to match the manifest information for this clip.
	The angles are 72" long with a slotted hole at one end. I would expect only a clip about 8" length.
Sunday, May 19, 2013	are not in a great rush to start installing these clips, it will not impact our schedule to wait for delivery of the correct materials.
	I told Andrew that we can wait if they want to send new. He said to give him time to confirm what VP wants to do. Later received email that VP is going to send someone to cut them. VP rep came and cut them today.
Monday, June 3, 2013	Issue Closed
3WT110 Oversiz	
Description:	The base trim for wall to roof at the lean to seems to be too wide. There is about 1/2" gap between vertical
	leg and the wall to roof flashing. The detail shows the seal at that front face with a screw every 12".
	The gap is so large that I don't think the seal will work. We have placed sealant on the top with intention to
	install the screw there unless otherwise directed.
	Emailed Andrew
Monday, June 17, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.
Monday, June 17, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing. Issue Closed
Monday, June 17, 2013 Roof To Wall Bas	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Isse Elevation         Monday, June 3, 2
Monday, June 17, 2013 Roof To Wall Bas	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         See Elevation         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost
Monday, June 17, 2013 Roof To Wall Bas	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu	Monday, June 3, 2         Issue Closed         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         ide Framing         Thursday, June 6, 2
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Monday, June 3, 2         Monday, June 6, 2         Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu	Monday, June 3, 2         Issue Closed         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         ide Framing         Thursday, June 6, 2
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Monday, June 6, 2         Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed       Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.       Issue Closed         ide Framing       Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation. No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Monday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Idde Framing       Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description:	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Idde Framing       Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing loosely in place we have the following issues:         -No clips to fasten the SBX319 & SBX316 beams to rafters. We have them tacked for now. Near as I can tell, the clips should have been welded in place on frame line 2 & 3.         -Similar clips required on Frame Line 2 for that end of the SBX016 beams. These bolt directly to Frame Line 1 which is the only connection of
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description:	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed       Monday, June 3, 2         Isse Elevation       Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed       Indee Framing         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing loosely in place we have the following issues:         -No clips to fasten the SBX316 beams to rafters. We have them tacked for now. Near as I can tell, the clips should have been welded in place on frame lines 2 & 3.
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description: Monday, June 10, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Monday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing loosely in place we have the following issues:         -No clips to fasten the SBX318 beams to rafters. We have them tacked for now. Near as I can tell, the clips should have been welded in place on frame line 2 & 3.         -Similar clips required on Frame Line 2 for that end of the SBX016 beams. These bolt directly to Frame Line 1 which is the only connection of any of the top beams that works as drawn.         -Header Channels, H2, are punched with holes 10-1/2" from the end. theare consplete so I don't know how many more issues we
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description: Monday, June 10, 2013 Monday, June 12, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Thursday, June 6, 2         Mide Framing         Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing losely in place we have the following issues:         -No clips to fasten the SBX318 & SBX316 beams to rafters. We have them tacked for now. Near as I can tell, the clips should have been welded in place on frame lines 2 & 3.         -So far, with most of the framing losely in place we have the SBX016 beams. These bolt directly to Frame Line 1 which is the only connection of any of the top
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description: Monday, June 10, 2013 ednesday, June 12, 2013 Friday, June 14, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Thursday, June 6, 2         Thursday, June 6, 2         Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation. No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing loosely in place we have the following issues:         -No clips to fasten the SBX318 & SBX316 beams to rafters. We have them tacked for now. Near as I can tell, the clips should have been welded in place on frame lines 2 & 3.         -Similar clips required on Frame Line 2 for that end of the SBX016 beams. These bolt directly to Frame Line 1 which is the only connection of any of the top beams that works as drawn.         -Header Channels, H2, are punched with holes 10-1/2" from the end. The holes should be 1-1/2" from the
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description: Monday, June 10, 2013 Monday, June 12, 2013 Friday, June 14, 2013 Monday, June 17, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed         Thursday, June 6, 2         Thursday, June 6, 2         Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation. No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing loosely in place we have the following issues:         -No clips to fasten the SBX318 & SBX316 beams to rafters. We have them tacked for now. Near as I can tell, the clips should have been welded in place on frame lines 2 & 3.         -Similar clips required on Frame Line 2 for that end of the SBX016 beams. These bolt directly to Frame Line 1 which is the only connection of any of the top beams that works as drawn.         -Header Channels, H2, are punched with holes 10-1/2" from the end. The holes should be 1-1/2" from the
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description: Monday, June 10, 2013 Monday, June 12, 2013 Friday, June 14, 2013 Monday, June 17, 2013 Tuesday, June 18, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing. Issue Closed         See Elevation       Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2" to make it work. This caused us to have to cut every wall sheet over the lean to. Issue Closed         dide Framing       Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation. No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots. The xobaces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing loosely in place we have the following issues: -No clips to fasten the SBX018 & SBX016 beams. These bolt directly to Frame Line 1 which is the only connection of any of the top beams that works as draw. -4eader Channels, H2, are punched with holes 10-1/2" from the end. The holes should be 1-1/2" from the end. -Braces, 03BA09110 are punched for 1/2" bolts, should be 3/4".       We are not yet complete so I don't know how many more issues we will find before we can get this finished. Andrew says the clips are in production. Welding detail and delivery schedule pending. We will stop roof short of the end bay today until this is completed. Drilling holes in header channels today. Andrew says the clips are expected Monday. Counting on the delivery today. The root is installed up to FL3 today and we need to weld the clips in to finish. The clips did not come yesterday, or if thy d
Monday, June 17, 2013 Roof To Wall Bas Description: Monday, June 3, 2013 Hangar Door Gu Description: Monday, June 10, 2013 Monday, June 12, 2013 Friday, June 14, 2013 Monday, June 17, 2013	Fabricator responded to issue, approved our recommendation to put the screws on horizontal leg of flashing.         Issue Closed         See Elevation       Monday, June 3, 2         The top of the wall to roof flash landed higher than expected. We had to move the support angle up almost 2° to make it work. This caused us to have to cut every wall sheet over the lean to.         Issue Closed       Interstand State (State Closed)         idde Framing       Thursday, June 6, 2         The details for the framing at the front wall are very difficult to erect. Nothing is set to any certain elevation.         No fixed points are given to work from. The front vertical posts hang from a slotted clip connected to another slotted clip which connects with more slots.         The cross beams have no provision for attachment to the rafters.         The x braces are welded detail. The guide support beam is a welded detail. That is very unusual and makes it more difficult to get a starting reference.         So far, with most of the framing loosely in place we have the following issues:         -No clips to fasten the SBX016 beams to rafters. We have them tacked for now. Near as I can tell, the clips should have been welded in place on frame lines 2 & 3.         -Similar clips required on Frame Line 2 for that end of the SBX016 beams. These bolt directly to Frame Line 1 which is the only connection of any of the top beams that works as draw.         -Hader Channels, H.2, are punched with holes 10-1/2° from the end. The holes should be 1-1/2° from the end.         -Braces, 03BA09110 are punched for 1/2° bolts, s

#### Project: Miami Executive Air, Type: Detail, Title: Hangar Door Guide Framing

Sunday, June 23, 2013	We have spent a tremendous amount of time going over the elevation and straightening this wall and still working on it. For all the slotted connections, we wind up with just about everything lifted as high as the slots allow. In some cases that is still a bit low. There is a very large deflection of the rafter, I would guess 3" or more, on each side. I don't know how much more that may wind up deflecting when the guide beams are installed.
	I am concerned that this deflection will be noticeable to the average person in the appearance of the rake flashing when viewed from certain locations at ground level.
	We keep straightening what we have for now intending to get it as close as possible but not welding anything solid. It will likely need another final pass adjusting after the doors are installed.
Thursday, June 27, 2013	Another full day of adjusting. Should have it complete tomorrow but no telling what will happen when they put the guide beams in place.
Tuesday, July 2, 2013	Nearly all finished welding off. Mike ran out of rods before finishing the kicker. Besides that we have left only the vertical x-braces to weld in case there is some last minute adjustment needed after they install the guide beams.
Saturday, July 6, 2013	Mike welded the kickers today.
Monday, July 8, 2013	Andrew says he'll have CO this week.
Friday, July 12, 2013	Received email copy of CO yesterday.
Friday, July 12, 2013	Issue Closed

## **Issue Type: Equipment**

Boom lifts	Thursday, May 9, 2013
Description:	2 Boomlifts, 60' from High Reach arrived 9am.
	600-201 and 600-187
Thursday, May 9, 2013	Issue Closed
Tuesday, May 14, 2013	600-201 had a hydraulic leak yesterday afternoon. Mechanic fixed it first thing this morning. It wasn't down for more than an hour or so.
Thursday, May 16, 2013	Two more arrive today.
	600-285 (brand new) and 600-163. The older one does not hold a key, falls out.
Monday, May 20, 2013	600-201 is still dripping oil and making a mess. Especially if it gets parked on slab overnight. I called Charles at HR2 and asked him to get it taken care of. Also ordered two more lifts for Thursday.
Tuesday, May 21, 2013	Tony, HR Mechanic, spent about an hour on the machine. Determined that he needs to order parts to fix. He used a second machine to work out of for that hour. He says the parts are going to be overnighted and someone will fix tomorrow.
Wednesday, May 22, 2013	Mechanic came and fixed the leak on 201 today during our lunch break.
Thursday, May 23, 2013	Two more lifts arrive first thing this morning. Both of them brand new machines. 600-288 & 600-290.
Friday, June 14, 2013	185 had a control problem. I called it in yesterday. Service came and replaced the control stalk complete. Said that it was fixed.
	I told him that 201 still has a puddle of hydraulic oil under it every morning. He looked at it. I don't know what he did or if it is better.
Tuesday, July 2, 2013	Told Charles to close each contract as they come to renew. 201 and 187 are up this week. They will move to Orion as of today. The others will move as they renew.
Friday, July 5, 2013	285 and 163 were moved to Orion today.

#### Crane Rental

Thursday, May 16, 2013 Description: Precision crane rental start today. One 70T to set the jack beam columns and assemble the beam. Onsite at 7am. Took till about 7:45 for Omar to show up and get us in the gate to go airside. Ready to work about 8:30. Second crane scheduled for tomorrow, Saturday. Hopefully finish crane work Monday. Sunday, May 19, 2013 Two cranes Friday and Saturday, set all the West side grids. Expecting to get the remainder of the grids up Monday.

- Tuesday, May 21, 2013 Cut short by rain yesterday. Hoping to finish today. Forecast is for more rain.
- Wednesday, May 22, 2013 Cranes out by around 3:30 yesterday. Wednesday, May 22, 2013 Issue Closed

#### Pettibone Won't Start

Friday, May 17, 2013

Monday, June 10, 2013

Description: Mario ran it out of fuel late Friday. They killed the battery trying to start it. Tried jump but no success. Put Calbert's charger on it, no improvement. I tried jump with my truck and then bought a new battery. Still wont start. Struggles to turn over after first full rotation. I assume it needs a new starter.

Sunday, May 19, 2013	
Monday, May 20, 2013	Javier, from Gordy's, arrived about 8am. Finished by 11:30.
Monday, May 20, 2013	Issue Closed

### Schedule Seamer Delivery

Schedule Seamer Delivery Thursday, May 23		
Description:	Confirm when we need seamer.	
Saturday, May 25, 2013	Sent Andrew an email that we should have the seamer by 5/7.	
Thursday, May 30, 2013	We could use seamer for the lean to roof now but if we had it, it would be idle all next week. I told Andrew get the wall to roof flashing installed and wait for the seamer to come as planned. Omar says he can get the seamer from Tropical Park. I said to him that to have it for one day, tomorrow, w	C C
Friday, May 31, 2013	Omar brought seamer at lunch time yesterday. Calbert started seaming lean to, finished up to where we s Andrew notified me that our seamer is expected early next week.	topped for masonry to finish.
Tuesday, June 11, 2013	No sign of seamer yet. We are roofing main roof and could use it now.	
Friday, June 14, 2013	Seamer is on the job. The guys have it on the roof. Nobody told me.	
Friday, June 14, 2013	Issue Closed	

#### Precision Boom Truck

Description: Set sheets up on roof for East side. Wally brought sheets in from Tarmac. Friday, June 14, 2013 Issue Closed

Saturday, June 15, 2013 Set sheets up on roof for West side. Mario and Ismael did a great job hustling and getting it done. Crane time 9:30 to 12:00 plus 2.

#### **Issue Type: Fabrication**

RBX 393 Holes		Wednesday, May 8, 2013
Description:	Bolt holes appear to be missing for connection to the jack beam.	
Thursday, May 9, 2013	Received drawing from VP via email from Andrew. Showed sketch with proper hole pattern.	
Thursday, May 16, 2013	Laid out and drilled holes yesterday.	

972 West Prospect Road, Fort Lauderdale, FL 33309 954-492-0661 954-492-0664

Thursday, May 16, 2013 Issue Closed

Strut Connectior	Plates	Monday, May 13, 2013
Description:	The plates for some of the roof struts connection do not match elevation on adja	cent frame. We find this
	problem at the second strut from line AL between frames 8-9 and 5-6.	
	RBX345 sets strut SBX306 2.5 inches from top of frame. At the opposite end of	the strut, the clip on
	RBX356 sets the strut top flange matching the top of frame height.	
	RBX378 sets the strut at 2.5 inches from the top of frame. At the opposite end o	f the strut, the top flange of
	the strut is at the top of frame.	
Tuesday, May 14, 2013		
Wednesday, May 15, 2013	VP response is that the problem is not structural, only aesthetic. Lemartec decision as to whether to correct it be.	t it or not. James told me to leave
Wednesday, May 15, 2013	Issue Closed	
RBX409 Purlin H	oles Missing	Monday, May 13, 2013
Description:	Endwall rafter piece appears to be missing a few holes. Unsure if the existing ho	les are in the proper
	location.	
Thursday, May 16, 2013	VP sent drawing with missing hole dimensions. Confirmed the holes that are there are correctly located.	
Wednesday, May 22, 2013	Drilled holes and installed purlins.	
Wednesday, May 22, 2013	Issue Closed	
Roof Bracing 06	3AB21016	Saturday, May 18, 2013
Description:	The most common size roof bracing, 2x2x3/16 21-1 3/4 long seems to have bee	n fabricated incorrectly.
	Manifest shows 96 pieces delivered. About half of those are 21-11 3/4, ten inche	es longer then required.
	We have those that are correct length installed, need to modify the others to kee	p from being delayed
	lifting the remaining grids.	
	5 55	
Monday, May 20, 2013	Set Mike and Delroy to start modifying angles first thing. Andrew sent confirmation of approval about 10:30 till 4:30 and did not quite finish them all	am. They worked on the braces
	till 4:30 and did not quite finish them all.	am. They worked on the braces
Monday, May 20, 2013 Tuesday, May 21, 2013 Wednesday, May 22, 2013		am. They worked on the braces
Tuesday, May 21, 2013	till 4:30 and did not quite finish them all. Mike and Delroy finished the angles at 1:00. Total of 29 man hours. Submitted change order request to Lemartec. I pressed for the change order in time to include in pay request but did not get it. Gene remarked that I was	being unfair. I have three
Tuesday, May 21, 2013 Wednesday, May 22, 2013	till 4:30 and did not quite finish them all. Mike and Delroy finished the angles at 1:00. Total of 29 man hours. Submitted change order request to Lemartec. I pressed for the change order in time to include in pay request but did not get it. Gene remarked that I was outstanding charges now, for a total of about \$8,000, that are not included in the contract figures and so ar	s being unfair. I have three re unbillable.
Tuesday, May 21, 2013 Wednesday, May 22, 2013	till 4:30 and did not quite finish them all. Mike and Delroy finished the angles at 1:00. Total of 29 man hours. Submitted change order request to Lemartec. I pressed for the change order in time to include in pay request but did not get it. Gene remarked that I was outstanding charges now, for a total of about \$8,000, that are not included in the contract figures and so an Andrew sent me an email saying to include in draw, but I don't want my schedule of values to become out	s being unfair. I have three re unbillable.
Tuesday, May 21, 2013 Wednesday, May 22, 2013	till 4:30 and did not quite finish them all. Mike and Delroy finished the angles at 1:00. Total of 29 man hours. Submitted change order request to Lemartec. I pressed for the change order in time to include in pay request but did not get it. Gene remarked that I was outstanding charges now, for a total of about \$8,000, that are not included in the contract figures and so ar	s being unfair. I have three re unbillable.
Tuesday, May 21, 2013 Vednesday, May 22, 2013 Friday, May 31, 2013	till 4:30 and did not quite finish them all. Mike and Delroy finished the angles at 1:00. Total of 29 man hours. Submitted change order request to Lemartec. I pressed for the change order in time to include in pay request but did not get it. Gene remarked that I was outstanding charges now, for a total of about \$8,000, that are not included in the contract figures and so an Andrew sent me an email saying to include in draw, but I don't want my schedule of values to become out processed so I did not add it.	s being unfair. I have three re unbillable.

Sunday, June 23, 2013Change order received yesterday.Sunday, June 23, 2013Issue Closed

### Additional Brace Angle Issues

Friday, May 31, 2013

Description:	We are not finding the correct angles for some of the remaining locations in wall and roof. I told Wally to install everything that works in order to narrow down and reduce the number of different angles we have to sort through. We will not modify anything until we have it all figured out.
	Victor voiced concern yesterday that we need to complete the bracing in the West sidewall. That is where
	we are having most of the issues. We do have one bay fully braced and several bays partial. I am confident
	that is enough for the structural integrity at this stage. We are working on completing the bracing now and
	will increase manpower on this once the endwall is finished today.
Monday, June 3, 2013	Down to the final braces and having to modify a significant number.
	We now have most of the braces in the sidewall that Victor was concerned about.
Tuesday, June 4, 2013	We find that the first angles from the eave at the interior bays are supposed to be 22' 2-1/2" but we have 23' 6-1/2". We do not find that length called for anywhere on the plans. We are modifying these to the length required (8 pieces).
	Same condition for that space in the end bay, length of angle does not match the length called for (4 more pieces).
	There are about 8-10 other angles that do not work. I expect we'll make them all work by the end of this day.
	Wally spoke to Brad Pease from VP about this issue while Brad was here cutting the clip angles. Brad declined the invitation to correct our brace angle issues and saw us start to modify them.
Tuesday, June 11, 2013	2 men, 12 hours spent correcting the angles.
Monday, June 17, 2013	Reminded Gene and Andrew about the change orders last week. Gene says he will take care of it. Andrew replied that he did not have the number until just now, is working on change order.
Monday, July 8, 2013	Andrew says he'll have CO this week.
	Received email copy of CO yesterday.
Friday, July 12, 2013	Issue Closed

## TCX002 Short

Thursday, June 13, 2013

Description:	Diagonal tubes marked TCX002 are nearly the same length as our TCX004. They should be considerably
	longer. They fall about 6' short of what they would need to be in order to work.
Friday, June 14, 2013	All the tube kickers are in besides these two at the center.
Tuesday, June 18, 2013	Andrew forwarded detail of "remedy". They are going to send a length of 6x6x3/8 tube to extend the short piece.
Thursday, June 27, 2013	Extension material came yesterday. Mike welded and installed them today.
Tuesday, July 2, 2013	It took about 8 manhours to complete but I am not going to chase after the change order. Just trying to wrap those already outstanding.
Tuesday, July 2, 2013	Issue Closed

Extended Deliver	ies Monday, March 18, 20
	Deliveries are spread out over four days, with one day idle. Site is not ready to erect so there is no other
Description.	work to make use of equipment. We have a short day, a skipped day then two short days. All the trucks
	could easily have been offloaded in two easy, productive, days.
	This schedule is costing significant money in equipment and labor as we stop and start, working less than
	full days with repeated mobilizations.
Friday, April 5, 2013	Gene assured me that he will compensate us by way of the pending insurance claim or change order.
Friday, April 5, 2013 Friday, May 31, 2013	Issue Closed Invoices created, at Gene's direction, and sent to Andrew have not been processed. No update as to status. Gene told me not to consider as
	change order, bill separately as its own job. There is no record of these charges other than the invoices.
	Issue Status Open- Follow Up Required Still pending payment of the invoices sent.
wonday, bune 17, 2010	Andrew stated the change orders have been approved in email.
	Change order received yesterday.
Sunday, June 23, 2013	
Additional Offloa	d Tuesday, March 19, 20
Description:	Two trucks that were scheduled to have arrived Monday, now expected Friday. I extended Precision crane
	schedule and planned for offloading an additional day.
Friday, April 5, 2013	
Friday, April 5, 2013	One of these trucks crashed and did not arrive until today.
Truck Crash	Friday, March 22, 20
Description:	One of the trucks expected today, originally scheduled for Monday, has been involved in an accident on
	the road. It will not be arriving today.
	They are returning the load to the plant to be checked and reloaded, will reschedule the delivery.
Friday, April 5, 2013 Friday, April 5, 2013	Materials arrived today, offloaded with Pettibone.
Filday, April 5, 2015	
Relocate Materia	ls Friday, April 5, 20
Description:	Wally, onsite for offload one truck, is told by Omar that he must relocate all the panels and materials that
	were offloaded on the grass. Omar says it must be done today, or they get fined. We were not aware of this
	until this moment. We could have started it yesterday or brought the crane and a couple extra guys today.
	Wally is getting as much as possible today but may not get it all. I made Gene and Andrew aware of that
	possibility.
	That material was placed exactly where we were told to place it at the time of receipt and this is all extra
	time, above and beyond the additional time already spent with the space constraints and the lag in
	deliveries.
	I spoke to Gene Owen and was told that he expects an invoice for the remobilization costs due to the
	delivery truck that crashed. He says he fully expects me to pad that number up to cover all my additional
	costs incurred. Submit separately, not as change order. If it doesn't get paid by the insurance claim, he will
	make it right another way, presumably by change order.
Saturday, April 6, 2013	
Saturday, April 6, 2013	
Insulation Deliver	ry Thursday, May 9, 20
	Not sure when it is scheduled for but I expect to be looking for it about May 24.
	Andrew says delivery scheduled for 5/20. I told him I would push towards the end of the week. He set it up for 5/23. Arrived first thing this morning.
Thursday, May 23, 2013 Thursday, May 23, 2013	
Dirt On Beams	Friday, May 17, 20
	It seems that some of the steel was shipped out with quite a bit of dirt on the web. Especially the jack
20001101011	frame. We washed down the jack beam while it was on the ground. The columns went up before we really
	thought about it. This steel was offloaded in single lifts from the truck bed to the asphalt. The dirt did not
	get on the steel while on the site.
Friday, May 17, 2013	5
Double Face Tap	e Friday, May 24, 20
	There was no tape sent with the insulation. We need it to start the lean to walls. We have a roll from one of
	our trucks but not enough to do much.
Saturday, May 25, 2013	Omar says he told Andrew and Gene, expects they will get by Tuesday. Victor says he had some at Tropical Park.
	We started with what we could find.
Tuesday, May 28, 2013	
Thursday, May 30, 2013 Friday, May 31, 2013	I brought two more rolls today. Omar expects delivery of the tape for this job today by noon. The tape did not come as expected yesterday. Omar says it will be here this morning.
	Omar found that the tape did arrive but was received by MEA office personnel. Omar will get it from them.
Friday, May 31, 2013	Issue Closed

972 West Prospect Road, Fort Lauderdale, FL 33309 954-492-0661 954-492-0664

Roof Screws Sh	ortage	Monday, June 17, 2013
	: We are just about out of roof screws for the clips.	
	Manifest shows 18,407 shipped. By quick rough estimate, 1 screws short of finishing the roof installation. Omar brought some from Tropical Park.	that seems about right but we are at least 5,000
Roof Clips Shor	tage	Monday, June 17, 201
	Roof crew ran out of 8" roof clips.	
Tuesday, June 18, 2013 Tuesday, June 18, 2013	550 8" clips 153 12" clips Omar brought us clips and screws. We roofed up to FL3 where we had to stop	
Caulking Shorta	ae	Thursday, June 20, 2013
	<ul> <li>We are running out of the panlastic butyl caulk for the roof.</li> <li>to finish. We need it for eave and endlaps of the few panel of and any other detail to finish.</li> </ul>	It is hard to guess how much we need in order
Sunday, June 23, 201 Sunday, June 23, 201	My guess is 30 or 40 of the sausage packs or tubes. Omar brought caulking to Mario Issue Closed	
sue Type: Personn		
Carlos Called C		Friday, May 24, 2013
Description Friday, May 24, 2013	Has an infection of some sort. Not work related. Ismael was Issue Closed	s aware that he was going to doctor.
Carlos Infection	Of Knee	Tuesday, May 28, 201
Thursday, May 30, 201: Thursday, May 30, 201:	of scratch that became infected. There was no report and h been hurting him for about a week. He believes be got som I reminded him and Ismael that all injuries need to be report must be notified and will follow up. He wants me to pay for the doctor. I said to submit the rece Carlos told me today that his knee is fine.	e kind of shaving or something in it. ted immediately, no matter how trivial, that I
Housekeeping		Friday, May 31, 201
	: It looks like Ismael's sheeting crew is leaving a trail behind	••••••
Saturday, June 1, 2013 Saturday, June 1, 2013	Emailed to Wally Wally had them clean up after themselves today. Issue Closed	
Delroy No Shov	I	Thursday, June 13, 201
	<ul> <li>Mike says he didn't get up.</li> <li>Gave Delroy counseling. Reminded him that we do not tolerate erratic attendar This, his first warning.</li> <li>Issue Closed</li> </ul>	nce.
Charles Jenkins	No Show	Saturday, June 15, 201
	Mike was unable to roust Charles for work this morning. Emphasized to Charles the importance of being reliable if he wants to remain w	
Charles Jenkins	No Work	Monday, June 17, 201
Description Tuesday, June 18, 2013 Tuesday, June 18, 2013		
James Out Sick		Friday, June 28, 201
Description	: James called Mike this morning and told him that he had so Yesterday he worked all day with me. Seemed to handle it j just tired, no telling.	ome kind of kidney stones or something.
Tuesday, July 2, 201	3 Issue Closed	

## Issue Type: Punchlist

Header Trim Deta	ail Tuesday, May 28, 2013
	Some of the header trims are terminated inside the rib of the wall panel. Extend and bring the backside
Decemption	outside of the panel to ensure no leaks.
	Ismael was working on that wall today, I told him to take care of the headers.
Saturday, July 6, 2013 Saturday, July 6, 2013	Ismael extended and corrected the trim. Issue Closed
Girt Clip Bolts	Tuesday, June 4, 201
Saturday, July 6, 2013	In the first door at South end of The lean to sidewall, no bolts in girt to clip at top of door jamb.
Saturday, July 6, 2013	
Correct The Elev	ation Of Portal Thursday, June 13, 201
Description:	One portal column at the lean to is too high at the base. Need to slot the holes at top or chip concrete
•	below.
	Delroy reamed the holes and bolted it as it stood.
Tuesday, July 2, 2013	Issue Closed
Purlin Braces Mis	ssing Thursday, June 13, 201
Description:	Was roofed over. Several locations on West side. I am not clear if we are missing the pieces or just didn't
	get it done in time. Different persons told me one or the other.
	Miguel was installing them today. Did not finish.
Monday, July 8, 2013 Thursday, July 11, 2013	Ismael plans to finish today. Ismael finished them.
Thursday, July 11, 2013	Issue Closed
Window Leaks	Friday, June 28, 201
Description:	3 out if four windows on the West side are leaking very badly. Water is sitting on the sill and running into
	the lap and corners of the sill flashing. They do not appear to be sealed at all.
	We need to get sealant into those laps, not just on the outside. This will leak forever if we do not fix it right.
	I sulled the land anast and shot applant is. Stood on the header and exammed it tight while refeatoring it
	I pulled the laps apart and shot sealant in. Stood on the header and crammed it tight while refastening it. Caulked the corners outside as that is all I could do with it. Did not see any leaks in the afternoon.
Saturday, July 6, 2013	Mario and Ismael checking the rest.
Saturday, July 6, 2013	
Flange Brace No	t Bolted Monday, July 8, 201
	Next to the personnel door at the NW corner. Needs to be drilled.
Thursday, July 11, 2013	Issue Closed
Weld Guide Sup	port Beams Tuesday, July 9, 201
Description:	We left the welding of the support beams for after they install the guide beams. We will wait to see if we get
	a significant deflection in case we need to raise them some more.
	The beams are being installed now.
Thursday, July 11, 2013	Spoke to one of the worker bees installing the doors. He remarked that the beams are all straight and didn't think any adjustment would be
Friday, August 9, 2013	needed. Mike finished last weekend.
Friday, August 9, 2013	Issue Closed
Type: Scope	
Hangar Door Rai	ls Tuesday, June 4, 201
Description:	The rails, along with the doors, are not in our scope of work. Andrew asked if we could do them and what
	the cost would be. I said we could do it for T&M and that I would guess the cost to be about \$2,200 (two
	guys, two days).
	I was concerned that it would impact our schedule causing us not to be prepared above when the door
	guys arrive next week. Andrew said the doors are delayed, that we will not need to be ready for them for
	another 2-3 weeks.
	Andrew said to go ahead and install the rails for T&M.
Saturday, June 15, 2013	Wally and I started laying out the rails today.
	Wally- 8 hours. Myself- 4 hours.
	Wally used Delroy some and Hugo helped most of the day.
Monday, June 17, 2013	Mike and Delroy start tacking them down this morning. Worked full day setting and tacking them. Wally and I spent several hours helping to
,,	be sure they were straight and proper. They gut the end rails to fit on account of the 2" bust.
,,,,,	be sure they were straight and proper. They cut the end rails to fit on account of the 2" bust. 2 men x 10 hours.

2 men x 10 hours.

 Thursday, June 20, 2013
 Finishing weld down rails today after the support beam clips.

 Finished at the end of the day.
 Additional 6 hours x 2 men.

 Monday, July 8, 2013
 Andrew says he'll have CO this week.

 Friday, July 12, 2013
 Received email copy of CO yesterday.

 Friday, July 12, 2013
 Issue Closed

### Hangar Door Guide Beams

Description: Gene Owen confirmed that the door guys will install the guide beams. Friday, June 14, 2013 Issue Closed Friday, June 14, 2013

## Issue Type: Site

Space For Offloa	d Wednesday, March 13, 20		
	The jobsite is very constrained. I don't see any way to get all the material offloaded in the space we have. We set most steel over the fence and all around the perimeter. All the sheeting, some secondary and the last truck that is coming Friday after having crashed enroute is outside the site. This will add quite a bit of inconvenience when time comes to to erect as we must locate and retrieve items as needed. Issue Closed		
Slab Delayed	Tuesday, April 9, 20		
	Scheduled to start erecting Monday 4/15. Omar warned me that it might slip a couple days. Andrew		
2000	notified me today that it would likely not be ready before Monday 4/22.		
Sunday, April 14, 2013	No word from Omar all week. I assume we are ready by 25th and I am planning for that.		
Friday, April 19, 2013	I called Omar to check if he'll be ready Monday. He says probably another week. Plan for the 29th now.		
Friday, April 26, 2013 Wednesday, May 1, 2013	3 The weather is pushing their intended last pour for main slab again. They expect now to pour Friday 5/3. We should still be able to start Monday 5/6 but the lean to slab will not be poured until later in the week.		
Monday, May 6, 2013	The first stage of the rails apron will also be poured some time later the next week likely. The weather was expected through the weekend which I assumed would further delay the pour. I pushed our start from Monday to be sure they would not be in our way.		
	Wally is moving crane to site and will verify ready for tomorrow start. Wally surveyed the site, the gate is not in place yet and neither is the ramp. They are just finishing the last of the big pours now. We decided to push one more day, start Wednesday.		
Tuesday, May 7, 2013 Tuesday, May 7, 2013	Andrew and Gene pressed for starting today. They got the gate done and said they were ready by the end of the day yesterday. I told them I had already redirected my crew but agreed to have a few guys on the job today to start organizing. Full crew start tomorrow.		
Slab Access	Wednesday, May 1, 20		
Description:	We are unable to pass the SE corner of the slab now that it goes nearly to the fence line. Omar is going to		
	add a gate gate to the fence so we can move equipment and materials through directly from airside.		
Monday, May 6, 2013	I also requested a ramp to get up onto the slab with equipment. Omar says they are building gate tomorrow. Same for the ramp.		
Tuesday, May 7, 2013 Tuesday, May 7, 2013	Omar had gate installed by the end of the day yesterday.		
Base Plate Level	ing Wednesday, May 8, 20		
Description:	The leveling nuts are not set to elevation. We need this ASAP in order to start erecting columns. Contractor		
	has someone stripping forms off the bolts now. Omar has been asked to address the elevation by getting		
	one bolt set at each location. We will level the rest of the bolts to match that one prior to setting a column.		
Wednesday, May 8, 2013	Omar set up a laser level an gave Mario a reference to set to. We did all the adjustments.		
Standing Water	Tuesday, May 21, 20		
Description:	After the rains last night, the slab has several inches of standing water.		
Tuesday, May 21, 2013	Omar eventually got a pump and the lake was pumped clear by mid afternoon. Everyone suffered wet feet.		
• •	After Omar pumped the slab dry, he cut the drain pipe open so that it would drain itself. After more days of rain, we find that the slab is once again a lake. It is not draining. The standing water makes it very difficult to work inside. We cannot run extension cords for power cords freely around the building to use power tools.		
Friday, May 31, 2013 Tuesday, June 4, 2013 Tuesday, June 4, 2013	Plumber opened the pipe this morning. Slab is, for the first, not a lake.		
Concrete Beam I	Placement Tuesday, May 28, 20		
Description:	The space from line 8 to the concrete beam at the lean to sidewall is called as 17'. The actual space is		
	16'-9 1/4". We'll need to cut the girts, if not the column.		
	Omar said to cut the girts to fit.		

t: Miami Executive Air,	Type: Site, Title: Masonry Not Finished	Report Date: Sunday, August 18, 2013, pg.	
Masonry Not Fin	ished	Friday, May 31, 201	
Description:	We cannot complete the lean to roof or wall until they fi endwall complete today, lacking one bay which must w They have to pour, lay more block, form grade beam an week.	rait on the masonry as well.	
Monday, June 3, 2013 Thursday, June 6, 2013 Friday, June 7, 2013	Subcontractor tells me he'll be done by Thursday. Wall over the lean to is sheeted up to the point that we are waiting for mas done until they finish. Poured concrete today. We still wait for forms to be stripped. Stripping forms and cleaning up today. We could get back on the lean to a		
Friday, June 7, 2013	will get to it when it works.		
Slack Anchor Lir	nes	Friday, May 31, 201	
Description:	There is too much slack in some of the safety lines. Spe The line at FL 1 needs straps to keep it on the roof and least 2 per side and one at the peak. I don't see any at the This needs to be corrected before we start filling in purl	ecifically FL 7 and FL 5. FL 10 needs a couple more of the same. I'd say at the Western half of the frame.	
Saturday, June 1, 2013 Saturday, June 1, 2013	Emailed to Wally. Wally had them fix the lines before working on purlins. Issue Closed		
Gate Can't Close	9	Thursday, June 13, 20 <sup>-</sup>	
Description: Thursday, June 13, 2013	The shoring for concrete is in the way of closing the gat Issue Closed	te. I called Omar, he said leave it open.	
Hangar Door Rai	ls Run Long	Saturday, June 15, 20	
Description:	Apparently the layout of the trough for the rails is a bit s	short. The rails will need to be cut a few inches	
Monday, June 17, 2013	His drawings show 255' span. We have cumulative length of 255-2. He says to cut them. Mike cut them this morning while in course of installing the rails. It took a couple hours with himself and Delroy. Will be included in the T&M of rails install.		
Monday, June 17, 2013			
e <b>Type: Subcontr</b> Plumber Cut Thr		Monday, July 8, 20	
	There is piping installed where the plumber cut huge sq		
Monday, July 8, 2013	first I have seen that technique. Not sure anyone would		
e Type: Weather			
Rain		Monday, May 20, 20	
Description: Monday, May 20, 2013	Lifting grids in morning. Heavy rain in the afternoon.		
Rain		Tuesday, May 21, 20	
Description:	Heavy rain as soon as we tried to start this morning. Spent about an hour watching radar and waiting for the cell to pass.		
Tuesday, May 21, 2013	Issue Closed		
Rain		Wednesday, May 22, 20	
Description: Wednesday, May 22, 2013	Showers throughout the day. Issue Closed		
Rain		Tuesday, May 28, 20	
	Big storms East, moving West. Managed to make a prowinds.	ductive day despite frequent showers and high	
Tuesday May 28, 2013	Issue Closed		

Tuesday, May 28, 2013 Issue Closed

### Rain

Wednesday, May 29, 2013

Description: Heavy rains and passing showers throughout the day. Wednesday, May 29, 2013 Issue Closed

Rain	Thursday, May 30, 2013	
Description:	Rained enough to stay wet, enough breaks to be productive. Wind picked up considerably. Mario finished roofing and tried to start lean to endwall but the wind was	
Thursday, May 30, 2013 Friday, May 31, 2013	tearing up the insulation so bad that he couldn't get anything done. Issue Closed	
Rain And Wind	Monday, June 3, 2013	
Description: Thursday, June 6, 2013	Showers and windy Issue Closed	
Rain And Wind	Tuesday, June 4, 2013	
Description: Thursday, June 6, 2013	Showers, light rain and windy Issue Closed	
Rain And Wind	Wednesday, June 5, 2013	
Description: Thursday, June 6, 2013	Showers and windy Issue Closed	
Rain And Wind	Thursday, June 6, 2013	
Description:	Very high winds today. Rainy morning. Planned to start roofing. Got just a starter roll down before stopping as the wind became too much.	
Thursday, June 6, 2013	Issue Closed	
Rain And Wind	Friday, June 7, 2013	
Description:	Light rain AM, heavy after lunch. Wind increasing as the day went on. Just managed to get the first bay or so of roof on.	
Friday, June 7, 2013		
Rain	Wednesday, June 12, 2013	
Description:	Rain late morning and some lightning. Stopped work, chased crew off the roof. Some rain, frequent light rain in the afternoon. Slowed production considerably all around.	
Friday, June 14, 2013	Issue Closed	
Rain	Thursday, June 13, 2013	
Description:	Torrential rain chased crew off the roof mid morning. They took an early lunch and were eventually able to get a start up on the West side.	
Friday, June 14, 2013	Issue Closed	
Heavy Rain	Tuesday, July 9, 2013	
Description: Tuesday, July 9, 2013	Just before lunch Issue Closed	