

Commercial Metal Building Services Corp

Issue Report

Project: Miami Executive Air
 Issue Title: RBX 393 Holes

Report Date: Sunday, August 18, 2013
 Produced By: Dean S. Davids

Issue Description

Bolt holes appear to be missing for connection to the jack beam.

| | |
|-----------------------------------------------------|-------------------------------------------|
| Conditions: <input type="checkbox"/> Affects Safety | <input type="checkbox"/> Affects Schedule |
|-----------------------------------------------------|-------------------------------------------|

Charges

Issue History

| | |
|------------------------|-----------------------------------------------------------------------------------------|
| Wednesday, May 8, 2013 | Issue discovered |
| Wednesday, May 8, 2013 | Issue reported |
| Thursday, May 9, 2013 | Received drawing from VP via email from Andrew. Showed sketch with proper hole pattern. |
| Thursday, May 16, 2013 | Laid out and drilled holes yesterday. |
| Thursday, May 16, 2013 | Issue Closed |

Issue Photos



